

1. Unzipped the EDID software to your PC.
2. Open the software and connect the monitor to your PC via HDMI cable.
3. Refresh to get the EDID from the monitor, select the file path and then drop the EDID data to LOCAL.. You will get the EDID file on the file path.

